### RECEIVED



**PUGET** SOUND KING COUNTY

AIR

POLIPIO 1996 CONTROL SNOHOMISH COUNTY

AGENCY

PIERCE COUNTY KITSAP COUNTY AGCW-SEATTLE

April 18, 1996

Gerry Brown Ash Grove Cement Co. 3801 E. Marginal Way S. Seattle, WA 98134

Dear Mr. Brown:

# Disposition of Notice of Violation No. 34415 PSAPCA Reg. No. 11339

Based on the information you provided to us in your corrective action letter dated March 21, 1996, this Agency considers the above-referenced matter closed and will take no further enforcement action in this case. We concur that the opacity monitor recorded steam forming inside the stack on December 5, 1995.

If you have any questions concerning this matter, please contagt me at 689-4078.

Sincere

Manager - Inspection

Rosemary G. Busterna, PSAPCA cc:

EMG\cbc

Dennis J. McLerran, Air Pollution Control Officer

DIRECTORS O F

> Lynn S. Horton, Mayor, Bremerton R.C. Johnson, Councilman, Snohomish County

AGCS2M001057

(206) 343-8800



PUGET SOUND

AIR

POLLUTION

CONTROL

AGENCY

KING COUNTY

KITSAP COUNTY

PIERCE COUNTY

SNOHOMISH COUNTY

April 18, 1996

RECEIVED

Gerry Brown Ash Grove Cement Co. 3801 E. Marginal Way S. Seattle, WA 98134 APR 2 5 1996 AGCW-SEATTLE

Dear Mr. Brown:

# Disposition of Notice of Violation No. 34413 PSAPCA Reg. No. 11339

Based on the information you provided to us in your corrective action letter dated March 21, 1996, this Agency considers the above-referenced matter closed and will take no further enforcement action in this case. We concur that the NOx excess emissions on December 21 and 22, 1995 were the result of an upset condition and are therefore exempt under the WAC 173-400-107(6).

If you have any questions concerning this matter, please contact the at 689-4078.

Sincerely,

Neal J. Shulman

Manager - Inspection

cc: Rosemary G. Busterna, PSAPCA

EMG\cbc

Dennis J. McLerran, Air Pollution Control Officer

BOARD OF DIRECTOR'S

Chairman: Win Granlund, Commissioner, Kitsap County Janet Chalupnik, Member at Large Edward D. Hansen, Mayor, Everett Lynn S. Horton, Mayor, Bremerton R.C. Johnson, Councilman, Snohomish County Gary Locke, King County Executive

Harold G. Moss, Mayor, Tacoma Norman B. Rice, Mayor, Seattle Doug Sutherland, Pierce County Executive



PUGET SOUND

AIR PC

KITSAP COUNTY

POLLUTION CONTROL

PIERCE COUNTY

L AGENCY SNOHOMISH COUNTY

March 12, 1996

Reg. No. 11339

Gerry Brown Ash Grove Cement Co. 3801 E Marginal Way S Seattle, WA 98134 RECEIVED

MAR1 3 1996 AGUVV-DEATTLE

Dear Mr. Brown:

The Agency has reviewed your December 1995 CEM Report and request for WAC 173-400-107 Unavoidable Excess Emissions exemption. The event was attributed to fuel switching from coal to natural gas and the overheating of the kiln. The Ash Grove Cement Plant Operation and Maintenance Plan does not show procedures to minimize emissions during fuel switching.

Please submit these procedures to the Agency within 10 days of receipt of this letter. These procedures should include corrective actions that will be taken to prevent excess emissions in the future. The copy of your procedures in our file is stamped DRAFT. Please submit your most current Operation and Maintenance Plan.

You referenced WAC 173-400-107 Section 4 for startup. However, Section 3 only exempts excess emissions as avoidable when there is a known cause. There is no discussion in your report identifying the cause, corrective actions and preventive measures. WAC 173-400-107 contains the criteria to adequately demonstrate a violation is unavoidable.

Please feel free to contact me if you have any questions.

Sincerely.

Fred Austin

Air Pollution Engineer

cc:

Elizabeth Gilpin, PSAPCA Melissa McAfee, PSAPCA Rosemary Busterna, PSAPCA

MM/cbc

Dennis J. McLerran, Air Pollution Control Officer

OARD OF DIRECTORS

Chairman: Win Granlund, Commissioner, Kitsap County Janet Chalupnik, Member at Large Edward D. Hansen, Mayor, Everett Lynn S. Horton, Mayor, Bremerton R.C. Johnson, Councilman, Snohomish County Gary Locke, King County Executive Harold G. Moss, Mayor, Tacoma Norman B. Rice, Mayor, Seattle Doug Sutherland, Pierce County Executive

Shutu

As with the latter, the December 5, 1995 event occurred prior to the introduction of feed to the system and with the main baghouse operating normally. The main baghouse had no problems prior to or following the event that would indicate a cause for an emission. The addendum to the CEM report stated that no cause for the opacity could be found and it cleared up on its own. The duration of the event seems consistant with the amount of refractory replaced. Therefore, we now believed that no emission occurred and the opacity readings were caused by steam condensing in the stack before the opacity monitor.

Please let me know if you have any further question.

Yours truly

Gerald J. Brown

Manager Safety and Environment

Copy: Henrik Voldbaek

Nate Fernow Trygve Hille

# ASH GROVE CEMENT COMPANY



March 20, 1996

Mr. Fred Austin,
Puget Sound Air Pollution Control Agency
110 Union Street, Suite 500`
Seattle, WA. 98101-2038

Re: Notices of Violation 34413 and 34415

Dear Mr. Austin:

Thank you for your March 13 letter requesting further information regarding the NOx emission of 12/21/95 and 12/25/95 referenced in NOV #34413 and the opacity measurement of 12/05/95 referenced in NOV #34415.

#### NOV #34413

NOx emissions above the 1 hour limit of 700 ppmc were reported as the result of an upset condition and exempt under WAC 173-400-107 (6) Excess emissions due to upsets. These events were caused by the emergency switching of fuels firing the kiln when hot spots or potential fires were detected in the pulverized fuel (coal) storage bin. The firing of the kiln was switched from coal to natural gas while the coal bin was emptied to eliminate the hot spot. This rapid switching of fuels to avert a potential emergency caused an unstable condition to occur in the kiln. The combination of firing the kiln with natural gas (which in general generates higher NOx than coal) and the upset condition in the kiln induced by the rapid fuel change generated the excessive NOx.

This event was not caused by nor the result of inadequate design, operation or maintenance and is not addressed in our current Operation and Maintenance Plan accompanying this response. Appropriate corrective actions were taken to stabilize the kiln and to reduce kiln temperature. As pointed out in the addendum to the December 1995 CEM Report, occasional hot spots or smoldering coal in the pulverized fuel bin is unavoidable despite our on going prevention efforts.

#### NOV #34415

The December 1995, an opacity measurement in excess of the 5% hourly average for 2 hours was reported and the addendum to the CEM report claimed a Start up exemption under WAC 173-400-107 (4). We now believe that the opacity monitor recorded steam forming inside the stack and that no emission had occurred. A section of refractory known to contain water was replaced in the kiln and during start up under cold weather conditions steam formed in the stack riser. The cause of the opacity reading was not immediately recognized as it had not occurred previously. A similar steam event occurred later on January 19, 1996. This event occurred after a much larger amount of refractory was replaced and because of its duration (10 hours), we were able to confirm the measured opacity was steam condensing in the stack before the opacity monitor.

## PUGET SOUND AIR POLLUTION CONTROL AGENCY

Registration No. 11339 Cert. Mail No. 7 035473352

Form No. 70-119 (Revised 9/93)

110 Union Street, Suite 500, Seattle, Washington 98101-2038 206-343-8800 / 1-800-552-3565 / Fax 206-343-7522

No. 34415

Signing this Notice is not an admission of guilt

AGCS2M001062

# NOTICE OF VIOLATION

Date of Violation: December	19.95		at	.m
Name	Responsible Person, Title			
Ash Grove Cement Co.	Gerry Brown Manager Environment			
Location of Violation (Address)	City	Zip	County	
3801 East Marginal Way So.	Seattle	98134	King	
Mailing Address	City, State	Zip	Phone ()	
as above	Seattle, WA	<i>(</i> 1	(206) 623-55	96
DID UNLAWFULLY CAUSE OR	ALLOW VIOLAT	ION OF:		
REGULATION OF THE PUGET SO  Section 5.05(e) Failure to develop and implement an operation and mainteners Section 6.09(b) Failure to obtain Notice of Construction approval prior to consection 9.03(a) Visible emissions in excess of 20% opacity for periods aggressection 9.04 Particulate matter deposited in quantities/characteristics/dures Section 9.11(a) Emission of air contaminant in quantities/characteristics/dures Section 9.12(b) Emission of odor-bearing air contaminants without use of best section 9.15(a) Emission of fugitive dust without use of best available control Section 9.15(c) Emission of fugitive dust from manufacturing process equipes Section 9.16 Failure to apply VOC-containing material using spray equipes Section 9.20 Failure to operate and maintain equipment in good working  Section 9.09 (b)(2) Uniqueful to Cause or allowed the Cause of allowed	egating more than 3 minutes/heation so as to be injurious or in ation so as to be injurious or in ation so as to be injurious or in est available control technology of technology.  I/debris on undercarriage (trackment or control apparatus. ment in an enclosed area with order.	hment of a source our.  Interfere with enjoy of the enjoy	ment of life/property.  /ment of life/property.  lage.  nd vertical stack.	
CORRECTIVE ACT	TION ORDER			
Under the provisions of Section 3.09 of Regulation I and RCW 70.94.211 you are ordered to the necessary corrective action you have taken or propose to take, including a schedule, to ac necessary corrective action:	submit a written report within hieve continuous compliance	ten (10) days of re with the regulation	eceipt of this Notice descri ns, <u>and</u> take the following	bing

# PUGET SOUND AIR POLLUTION CONTROL AGENCY 110 Union Street, Suite 500, Seattle, Washington 98101-2038

Registration No. 113

Form No. 70-119 (Re sed 9/93)

206-343-8800 / 1-800-552-3565 / Fax 206-343-7522

No. 34413

Signing this Notice is not an admission of guilt

AGCS2M001063

NOTICE OF V	IOLATION				
Date of Violation:	, 19 <u>95</u>		atm.		
Name	Responsible Person, Title				
Ash Grove Cement Co.	Gerry Brown Enviro, Manager				
Location of Violation (Address)	City	Zip	County		
3801 East Marginal Way So.	Seattle	98134	King		
Mailing Address	City, State	Zip	Phone C		
as above	Scattle, WA.	1)	(206) 623-5596		
DID UNLAWFULLY CAUSE OR A	ALLOW VIOLAT	ION OF:			
REGULATION OF THE PUGET SOUND AIR POLLUTION CONTROL AGENCY FOR:					
□ Section 5.05(e) Failure to develop and implement an operation and maintenant Section 6.03(a) Failure to obtain Notice of Construction approval prior to construction 6.09(b) Failure to meet conditions of an Order of Approval.  □ Section 9.03(a) Visible emissions in excess of 20% opacity for periods aggregation of section 9.04 Particulate matter deposited in quantities/characteristics/dural Emission of air contaminant in quantities/characteristics/dural Emission of odor-bearing air contaminants without use of best section 9.15(a) Emission of fugitive dust without use of best available control of Section 9.15(b) Operation of vehicle on paved public roadway with dirt/mud/ □ Section 9.16 Emission of fugitive dust from manufacturing process equipment of Section 9.20 Failure to apply VOC-containing material using spray equipment of Section 9.20 Failure to operate and maintain equipment in good working of Section Section 9.20 Section	gating more than 3 minutes/hotion so as to be injurious or interest available control technology of technology. I debris on undercarriage (trackment or control apparatus. The in an enclosed area with the order.	erfere with enjoy terfere with enjoy out) or load spill filtered exhaust ar	ment of life/property.  ment of life/property.  age.  ad vertical stack.  Average		
FACTS ALLEGED TO CONSTITUTE A VIOLATION	to meet Not	ice of C	onstruction.		
number 5730 Condition 6(B) I hour av	erage Nox lin	ait trop	n the main		
Stack at 3801 E. Marginal Way So. in Seattle.					
CORRECTIVE ACT	TION ORDER				
Under the provisions of Section 3.09 of Regulation I and RCW 70.94.211 you are ordered to s the necessary corrective action you have taken or propose to take, including a schedule, to ach necessary corrective action:	submit a written report within this in the continuous compliance v	ten (10) days of re vith the regulation	eceipt of this Notice describing is, and take the following		
Mila dila 3/12/96	Paceived By				